PRODUCT DISCONTINUANCE BULLETIN



Issue Date: August 4, 2008 PDB Number: PDB_bc637PCI-U.pdf

Product

Symmetricom bc637PCI-U GPS Synchronized Time and Frequency processor card





Discontinued: bc637PCI-U

Replacement: bc637PCI-V2

Overview

Symmetricom is announcing the discontinuance of the bc637PCI-U GPS Synchronized Time and Frequency processor card. This model contains obsolete parts no longer available in the market. The replacement bc637PCI-V2 is 100% form and fit compatible. Minor functional changes have been made along with added features. See the product change notice (PCN) dated August 2008 for complete details regarding all changes. Note: the bc635PCI-U model is not affected by this discontinuance, though users are encouraged to migrate from the bc635PCI-U to the newer bc635PCI-V2.

Product Obsolescence Timeline

Milestone	Date	
Last Day to Order	While supplies last.	
Extended Warranty Contracts (maximum expiration date)	September 2012	
Repair End Date (Out-of-warranty repairs will not be available for this product beyond this date)	September 2012	
Customer Support Contracts (non-repair services)	Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Customers can contact SGS for service availability and terms.	

Affected Models and Replacement Product Summary

Current Models	Current Part #s	Replacement Models	Replacement Part #s
bc637PCI-U	bc637PCI-U	bc637PCI-V2	bc637PCI-V2
bc637PCI-U-OCXO	bc637PCI-U-OCXO	bc637PCI-V2-OCXO	bc637PCI-V2-OCXO

Support Policy

Repair services and maintenance contracts are expected to be available for 4 years from the product's discontinuance date. In the event of parts or component obsolescence, repairs will be made on a best efforts basis. All other service options (spares support, telephone technical support, on-site maintenance, training, etc.) are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA

1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA

1-408-428-7907 worldwide support@symmetricom.com www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.

Santa Rosa, CA 95403 Telephone: 707-528-1230 Facsimile: 707-527-6640